# Oil Field Environmental Incident Summary

**Responsible Party:** OXY USA INC. **Well Operator:** OXY USA INC. **Well Name:** CABERNET SWD 1

Field Name: CABERNET Well File #: 90174

Date Incident:2/16/2015Time Incident:07:40Facility ID Number:County:DUNNTwp:144Rng:97Sec:34Qtr:

Location Description:

Submitted By: Robyn Espinoza Received By:

Contact Person: Robyn Espinoza

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.8 MileDistance Nearest Water Well:0.8 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 4 Barrels 4 Barrels 4 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 4/10/2015 Clean Up Concluded: 3/10/2015

Risk Evaluation:

Contaminated surface material

Areal Extent:

## Potential Environmental Impacts:

Contaminated surface material

### Action Taken or Planned:

A block valve was installed to isolate the line and prevent any further release, the line was sucked out and a vac truck was dispatched to recover all standing liquids

Wastes Disposal Location: TBD

Agencies Involved:

#### **Updates**

Date: 2/18/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.